



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining


MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

January 31, 2013

Reviewed: 

|   |   |
|---|---|
| <b>Mine Name:</b> Devil's Slide Quarry  | <b>Permit Number:</b> M/029/0001          |
| <b>Operator Name:</b> Holicum (US) Inc. | <b>Inspection Date:</b> November 03, 2010 |
| <b>Inspector(s):</b> L Hepler           | <b>Time:</b> 8:00 AM                      |
| <b>Other Participants:</b> Ken George   | <b>Mine Status:</b> Active                |

| Elements of Inspection  | Evaluated                           | Comment                             | Enforcement              |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds                            | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls)         | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control                      | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 4. Deleterious Material   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety)           | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 6. Reclamation  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts) | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |
| 8. Soils  | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Revegetation   | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> |

**Bond Renewal Date:** 08-30-2012 **Bond Amount:** \$5,000,000 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection. This site was last inspected on 07-05-2007.

**Inspection Summary:** Toured the mine, surrounding area, and facilities. Currently the Operator is working on a permit amendment. Photos were taken to document site conditions of the site.

**Conclusions and Recommendations:** The Operator needs to complete the amendment to the NOI. Maintenance of sediment ponds should be done on a regular basis. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

LAH:eb

cc Holicum - Ken George

BLM - [Larry\\_Garahana@blm.gov](mailto:Larry_Garahana@blm.gov)

O:\M029-Morgan\M0290001-DevilsSlide\inspections\Insp-11032010.doc





Upper sediment pond



Upper sediment pond



Lower sediment pond, berm and Weber river




Berm for upper sediment pond and Weber river





Reclaimed area



Push back



Early morning photo of mine



Main Highwall